

Oil Field Environmental Incident Summary

Incident: 20140928174235 **Date/Time of Notice:** 09/28/2014 17:42

Responsible Party: CONDOR PETROLEUM, INC.

Well Operator: CONDOR PETROLEUM, INC.

Well Name: FEDERAL 2-28

Field Name: TREE TOP

Well File #: 8116

Date Incident: 9/26/2014 **Time Incident:** 07:00

Facility ID Number:

County: BILLINGS

Twp: 142

Rng: 100

Sec: 28

Qtr:

Location Description: hole in the treater, inside the dike

Submitted By: Corey Hutzenbeler

Received By:

Contact Person: Ron Condor
216 16TH STREET SUITE 1750
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	15	Barrels	15	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

none

Potential Environmental Impacts:

None

Action Taken or Planned:

washed out treater washed the dike area and sucked up all water. will repair treater if repairable, if not we will get a new one

Wastes Disposal Location: We put all fluid in the water tank

Agencies Involved:

Updates

Date: 9/29/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater leak, remained on location according to the report. NDIC retains oversight.